

MANDATORY**SEL-79-03****TITLE**OIL - TRANSMITTAL OF CONTINENTAL AEROSPACE TECHNOLOGIES CSB07-1A CONNECTING ROD
PISTON PIN BUSHING INSPECTION**EFFECTIVITY**

All airplane serial numbers for the following Cessna and Beechcraft models that have a Continental A Series, C Series, E Series, O-200, O-300, GO-300, IO-346, IO-360, O-470, IO-470, IO-520, IO-550, TSIO-520, TSIO-550, TSIOF-550 aviation gasoline (AvGas) engine installed.

CESSNA MODELS

MODEL	SERIAL NUMBERS
120-140	8000 thru 15075
140A	15200 thru 15724
150	17001 thru 17999, 59001 thru 59018
150A	628, 15059019 thru 15059350
150B	15059351 thru 15059700
150C	15059701 thru 15060087
150D	15060088 thru 15060772
150E	644, 15060773 thru 15061532
150F	15061533 thru 15064532
150G	15064533 thru 15067198
150H	15067199 thru 15069308
150J	15069309 thru 15071128
150K	15071129 thru 15072003
150L	15072004 thru 15075781
150M	15075782 thru 15079405
A150K	A1500001 thru A1500226
A150L	A1500227 thru A1500523
A150M	A1500524 thru A1500734, 15064970
A-150L	A-1501001 thru A-1501039
A-A150L	A-A1500001 thru A-A1500009
F150F	F150-0001 thru F150-0067
F150G	F150-0068 thru F150-0219
F150H	F150-0220 thru F150-0389
F150J	F150-0390 thru F150-0529
F150K	F15000530 thru F15000658

April 21, 2021

SEL-79-03
Page 1 of 8

Textron Aviation Customer Service, P.O. Box 7706, Wichita, KS 67277, U.S.A. 1-316-517-5800

This document contains technical data and is subject to U.S. export regulations. This information has been exported from the United States in accordance with export administration regulations. Diversion contrary to U.S. law is prohibited. ECCN: 9E991

MANDATORY

SEL-79-03

F150L	F15000659 thru F15001143
F150M	F15001144 thru F15001428
FA150K	FA1500001 thru FA1500081
FA150L	FA1500082 thru FA1500120
170	18000 thru 18729
170A	18730 thru 20266
170B	20267 thru 27169
172	28000 thru 29999, 36000 thru 36999, 46001 thru 46754
172A	625, 46755 thru 47746
172B	17247747 thru 17248734
172C	17248735 thru 17249544
172D	17249545 thru 17250572
172E	17250573 thru 17251822
172F	17251823 thru 17253392
172F (T-41A)	17251947 thru 17253392
172G	17253393 thru 17254892
172G (T-41A)	17254405 thru 17254544
172H	17254893 thru 17256512
172H (T-41A)	17256280 thru 17256346
P172D	P17257120 thru P17257188
FP172	FP172-001 thru FP172-0003
F172D	F172-0001 thru F172-0018
F172E	F172-0019 thru F172-0085
F172F	F172-0086 thru F172-0179
F172G	F172-0180 thru F172-0319
F172H	F172-0320 thru F172-0654, F17200655 thru F17200754
F172K	F17200755 thru F17200804
FR172E	FR17200001 thru FR17200060
FR172F	FR17200061 thru FR17200145
FR172G	FR17200146 thru FR17200225
FR172H	FR17200226 thru FR17200350
FR172J	FR17200351 thru FR17200590
FR172K	FR17200591 thru FR17200675
R172E (T-41B, T-41C)	R172-0001 thru R172-0335
R172F (T-41D)	R172-0336 thru R172-0409

MANDATORY**SEL-79-03**

R172G (T41C, T-41D)	R1720410 thru R1720444
R172H (T41D)	R1720445 thru R1720625
R172J	P17257189
R172K	680, R1722000 thru R1723454
175	55001 thru 56238
175A	619, 56239 thru 56777
175B	17556778 thru 17557002
175C	17557003 thru 17557119
180	614, 30000 thru 32661
180A	32662 thru 32999, 50001 thru 50355
180B	50356 thru 50661
180C	624, 50662 thru 50911
180D	18050912 thru 18051063
180E	18051064 thru 18051183
180F	18051184 thru 18051312
180G	18051313 thru 18051445
180H	18051446 thru 18052284
180J	18052285 thru 18052489, 18052491 thru 18052770
180K	18052490, 18052771 thru 18053203
182	613, 33000 thru 33842
182A	33843 thru 34753, 34755 thru 34999, 51001 thru 51556
182B	34754, 51557 thru 51622, 51624 thru 52358
182C	631, 52359 thru 53007
182D	51623, 18253008 thru 18253598
182E	18253599 thru 18254423
182F	18254424 thru 18255058
182G	18255059 thru 18255844
182H	634, 18255846 thru 18256684
182J	18255845, 18256685 thru 18257625
182K	18257626 thru 18257698, 18257700 thru 18258505
182L	18258506 thru 18259305
182M	18257699, 18259306 thru 18260055
182N	18260056 thru 18260825
182P	675, 18260826 thru 18263478, 18263480 thru 18265175

MANDATORY

SEL-79-03

182Q	18263479, 18265176 thru 18267301, 18267303 thru 18267715
182R	643, 18267302, 18267716 thru 18268615
A182J	A182-0001 thru A182-0056
A182K	A182-0057 thru A182-0096
A182L	A182-0097 thru A182-0116
A182N	A182-0117 thru A182-0148
F182P	F18200001 thru F18200025
F182Q	F18200026 thru F18200169
FR182	FR18200001 thru FR18200070
185	185-0001 thru 185-0237
185A	185-0238 thru 185-0512
185B	185-0513 thru 185-0653
185C	185-0654 thru 185-0776
185D	185-0777 thru 185-0967
185E/A185E	185-0968 thru 185-1149
A185E	185-1150 thru 185-1934, 18501833 thru 18502090
A185F	18502091 thru 18504448
188/A188	651, 188-0001 thru 188-0572
A188/A188A	18800573 thru 18800832
188B	18800833 thru 18802348
A188B	18800833 thru 18803973, 18800967T thru 18803973T
T188C	T18802839T, T18803307T, T18803308T, T18803325T thru T18803974T
A-A188B	A-A1880001 thru A-A1880034
210-5 (205)	205-0001 thru 205-0480
210-5A (205A)	205-0481 thru 205-0577
206	206-0001 thru 206-0275
U206	U206-0276 thru U206-0437
U206A/TU206A	U206-0438 thru U206-0656
U206B/TU206B	U206-0657 thru U206-0914
U206C/TU206C	U206-0915 thru U206-1234
U206D/TU206D	U206-1235 thru U206-1444
U206E/TU206E	U20601445 thru U20601700
U206F/TU206F	U20601701 thru U20603521
U206G/TU206G	676, U20603522 thru U20607020

MANDATORY**SEL-79-03**

P206	P206-0002 thru P206-0160
P206A/TP206A	P206-0161 thru P206-0306
P206B/TP206B	P206-0307 thru P206-0419
P206C/TP206C	P206-0420 thru P206-0519
P206D/TP206D	P206-0520 thru P206-0603
P206E/TP206E	P206-00001, P20600604 thru P20600647
207/T207	20700001 thru 20700362
207A/T207A	20700363 thru 20700788
210	57001 thru 57575
210A	21057576 thru 21057840
210B	21057841 thru 21058085
210C	21058086 thru 21058220
210D	21058221 thru 21058510
210E	21058511 thru 21058715
210F	21058716 thru 21058818
210G	21058819 thru 21058936
210H	21058937 thru 21059061
210J	21059062 thru 21059199
210K/T210K	21059200 thru 21059502
210L/T210L	21059503 thru 21061573
210M/T210M	21061042, 21061574 thru 21062954
210N/T210N	21062955 thru 21064897
210R/T210R	21064898 thru 21065009
P210N	P21000001 thru P21000834
P210R	P21000835 thru P21000874
T210F	T210-0001 thru T210-0197
T210G	T210-0198 thru T210-0307
T210H	T210-0308 thru T210-0392
T210J	21058140, T210-0393 thru T210-0454
T240	T24000001 thru T24002146
300 (LC40-550FG)	40001 thru 40079
350 (LC42-550FG)	42001 thru 42084, 42501 thru 42569, 421001 thru 421020
400 (LC41-550FG)	41002 thru 41108, 41501 thru 41533, 41563 thru 41800, 411001 thru 411161

BEECHCRAFT MODELS**MODEL****SERIAL NUMBERS**

MANDATORY

SEL-79-03

A23	M-3, M-555 thru M-900
E33	CD-1119 thru CD-1234
F33	CD-1235 thru CD-1254
G33	CD-1255 thru CE-1304
E33A	CE-180 thru CE-289
E33C	CJ-1 thru CJ-25
F33A	CE-290 thru CE-1791
F33C	CJ-26 thru CJ-179
35-33	CD-1 thru CD-224, CD-233, CD-234, CD-236, CD-241, CD-246 thru CD-250
35-A33	CD-225 thru CD-232, CD-235, CD-237 thru CD-240, CD-242, CD-245, CD-251 thru CD-387
35-B33	CD-388 thru CD-813
35-C33	CD-814 thru CD-1118
35-C33A	CE-1 thru CE-179
35	D-1 thru D-1500
A35	D-1501 thru D-2200, D-15001
B35	D-2201 thru D-2680
C35	D-2681 thru D-3292, D-3294 thru D-3400
D35	D-3401 thru D-3698
E35	D-3293, D-3699 thru D-3998
F35	D-3999 thru D-4375, D-4377 thru D-4391
G35	D-4376, D-4392 thru D-4865, D-15002
H35	D-4866 thru D-5061, D-5063 thru D-5330
J35	D-5062, D-5331 thru D-5725
K35	D-5726 thru D-6161
M35	D-6162 thru D-6561
N35	D-6562 thru D-6841
P35	D-6842 thru D-7139, D-7141 thru D-7309
S35	D-7140, D-7310 thru D-7976
V35	D-7977 thru D-8598
V35A	D-8599 thru D-9068
V35B	D-9069 thru D-10403
36	E-1 thru E-184
A36	E-185 thru E-3629, E-3631 thru E-3635
A36TC	EA-1 thru EA-241, EA-243 thru EA-272
B36TC	EA-242, EA-273 thru EA-697

MANDATORY**SEL-79-03**

G36

E-3630, E-3636 thru E-4146

REASON

There have been reports from the field of piston pin bushing material being found in the oil sump and/or the oil filter. Continental Aerospace Technologies has released Revision A to Critical Service Bulletin CSB07-1A which has been extensively revised and provides inspection instructions for the connecting rod piston pin bushing and also includes additional instructions to strain the oil and inspect the oil filter media during routine oil changes. In addition to the expanded inspection, Revision A of CSB07-01 has Instructions for Continued Airworthiness (ICA) that must be placed into specified manuals as listed in Revision A of CSB07-01.

DESCRIPTION

This service document transmits Continental Aerospace Technologies CSB07-01 Revision A, Inspection of the connecting rod pin piston bushing.

COMPLIANCE

MANDATORY. Refer to the Continental Aerospace Technologies Critical Service Bulletin CSB07-01 Revision A for compliance information.

A service document published by Textron Aviation may be recorded as *completed* in an aircraft log only when the following requirements are satisfied:

- 1) The mechanic must complete all of the instructions in the service document, including the intent therein.
- 2) The mechanic must correctly use and install all applicable parts supplied with the service document kit. Only with written authorization from Textron Aviation can substitute parts or rebuilt parts be used to replace new parts.
- 3) The mechanic or airplane owner must use the technical data in the service document only as approved and published.
- 4) The mechanic or airplane owner must apply the information in the service document only to aircraft serial numbers identified in the *Effectivity* section of the document.
- 5) The mechanic or airplane owner must use maintenance practices that are identified as acceptable standard practices in the aviation industry and governmental regulations.

No individual or corporate organization other than Textron Aviation is authorized to make or apply any changes to a Textron Aviation-issued service document or flight manual supplement without prior written consent from Textron Aviation.

Textron Aviation is not responsible for the quality of maintenance performed to comply with this document, unless the maintenance is accomplished at a Textron Aviation-owned Service Center.

CONSUMABLE MATERIAL

No specialized consumable materials are required to complete this service document.

TOOLING

No specialized tooling is required to complete this service document.

REFERENCES

Applicable Model Maintenance/Service Manual

Continental Aerospace Technologies Critical Service Bulletin CSB07-01, Revision A, dated September 02, 2020.

PUBLICATIONS AFFECTED

None.

MANDATORY**SEL-79-03****ACCOMPLISHMENT INSTRUCTIONS**

1. Prepare the airplane for maintenance.
 - A. Make sure that the airplane is electrically grounded.
 - B. Make sure that all switches are in the OFF/NORM position.
 - C. Disconnect electrical power from the airplane.
 - (1) Disconnect the airplane battery.
 - (2) Disconnect external electrical power.
 - D. Attach maintenance warning tags to the battery and external power receptacle that have **"DO NOT CONNECT ELECTRICAL POWER - MAINTENANCE IN PROGRESS"** written on them.
2. Remove the engine cowling. (Refer to the Appropriate Model Maintenance or Service Manual.)
3. Complete the Continental Aerospace Technologies Critical Service Bulletin CSB07-01 Revision A.
4. Install the engine cowling. (Refer to the Appropriate Model Maintenance or Service Manual.)
5. Remove the maintenance warning tags and connect the airplane battery.
6. Make an entry in the airplane logbook that states compliance and method of compliance with this service document.

TITLE

OIL - TRANSMITTAL OF CONTINENTAL AEROSPACE TECHNOLOGIES CSB07-1A CONNECTING ROD
PISTON PIN BUSHING INSPECTION

TO:

Aircraft Owner of the Cessna and Beechcraft Models as follows:

CESSNA MODELS

120-140, 140A, 150, 150A, 150B, 150C, 150D, 150E, 150F, 150G, 150H, 150J, 150K, 150L, 150M, A150K, A150L, A150M, A-150L, A-A150L, F150F, F150G, F150H, F150J, F150K, F150L, F150M, FA150K, FA150L, 170, 170A, 170B, 172, 172A, 172B, 172C, 172D, 172E, 172F, 172F (T-41A), 172G, 172G (T41A), 172H, 172H (T-41A), P172D, FP172, F172D, F172E, F172F, F172G, F172H, F172K, FR172E, FR172F, FR172G, FR172H, FR172J, FR172K, R172E (T-41B, T-41C), R172F (T-41D), R172G (T-41C, T-41D), R172H (T-41D), R172J, R172K, 175, 175A, 175B, 175C, 180, 180A, 180B, 180C, 180D, 180E, 180F, 180G, 180H, 180J, 180K, 182, 182A, 182B, 180C, 180D, 182E, 182F, 182G, 182H, 182J, 182K, 182L, 182M, 182N, 182P, 182Q, 182R, A182J, A182K, A182L, A182N, F182P, F182Q, FR182, 185, 185A, 185B, 185C, 185D, 185E/A185E, A185E, A185F, 188/A188, A188/A188A, 188B, A188B, T188C, A-A188B, 210-5 (205), 210-5A (205A), 206, U206, U206A/TU206A, U206B/TU206B, U206C/TU206C, U206D/TU206D, U206E/TU206E, U206F/TU206F, U206G/TU206G, P206, P206A/TP206A, P206B/TP206B, P206C/TP206C, P206D/TP206D, P206E/TP206E, 207/T207, 207A/T207A, 210, 210A, 210B, 210C, 210D, 210E, 210F, 210G, 210H, 210J, 210K/T210K, 210L/T210L, 210M/T210M, 210N/T210N, 210R/T210R, P210N, P210R, T210F, T210G, T210H, T210J, T240, 300 (LC40-550FG), 350 (LC42-550FG), 400 (LC41-550FG)

BEECHCRAFT MODELS

A23, E33, F33, G33, E33A, E33C, F33A, F33C, 35-33, 35-A33, 35-B33, 35-C33, 35-C33A, 35, A35, B35, C35, D35, E35, F35, G35, H35, J35, K35, M35, N35, P35, S35, V35, V35A, V35B, 36, A36, A36TC, B36TC, G36

REASON

There have been reports from the field of piston pin bushing material being found in the oil sump and/or the oil filter. Continental Aerospace Technologies has released Revision A to Critical Service Bulletin CSB07-01 which has been extensively revised and provides inspection instructions for the connecting rod piston pin bushing and also includes additional instructions to strain the oil and inspect the oil filter media during routine oil changes. In addition to the expanded inspection, Revision A of CSB07-01 has Instructions for Continued Airworthiness (ICA) that must be placed into specified manuals as listed in Revision A of CSB07-01.

COMPLIANCE

MANDATORY. Refer to the Continental Motors Inc. Critical Service Bulletin CSB07-01 Revision A for compliance information.

LABOR HOURS**WORK PHASE**

Inspection

LABOR-HOURS

As Necessary

MATERIAL AVAILABILITY

No part are required to complete this service document.

April 21, 2021

SEL-79-03
Page 1 of 2

Textron Aviation Customer Service, P.O. Box 7706, Wichita, KS 67277, U.S.A. 1-316-517-5800

This document contains technical data and is subject to U.S. export regulations. This information has been exported from the United States in accordance with export administration regulations. Diversion contrary to U.S. law is prohibited. ECCN: 9E991

WARRANTY

NONE

NOTE: As a convenience, service documents are now available online to all our customers through a simple, free-of-charge registration process. If you would like to sign up, please visit the Customer Access link at www.txtavsupport.com to register.

CONTINENTAL AEROSPACE TECHNOLOGIES™
CRITICAL SERVICE BULLETIN

COMPLIANCE NECESSARY TO MAINTAIN SAFETY

CATEGORY 2
CSB07-01A

Supersedes SB07-1
TECHNICAL PORTIONS
FAA APPROVED

SUBJECT: Connecting Rod Piston Pin Bushing Inspection
PURPOSE: Provide inspection instructions for the connecting rod piston pin bushing
COMPLIANCE: At each cylinder removal or anytime piston pin bushing material is identified during routine maintenance

MODELS

AFFECTED: Continental Aerospace Technologies new and rebuilt A Series, C Series, E Series, O-200, IO-240, IOF-240, GO-300, O-300, IO-346, IO-360, LTSIO-360, TSIO-360, GIO-470, O-470, IO-470, TSIO-470, IO-520, GTSIO-520, LTSIO-520, TSIO-520, IO-550, IOF-550, TIARA, TSIO-550, TSIOF-550, and TSIOL-550 engine models.

I. GENERAL INFORMATION

Continental Aerospace Technologies, Inc. (Continental™) has received reports from the field of piston pin bushing material being found in the oil sump or the oil filter. Piston pin bushings are manufactured from steel-backed bronze and are curved on a radius of approximately 0.62" (see Figure 1).



BUSHING SPLIT LINE

Figure 1. Typical New Piston Pin Bushings

II. OIL CHANGE

Straining engine oil and during the oil change and inspecting the oil filter media is the least invasive method to determine if connecting rod piston pin bushing material has separated from the connecting rods.

ISSUED
2007/03/19

REVISED
2020/09/02



DOC NO
CSB07-01

REVISION
A

PAGE
1 of 6

1. Perform the oil change at the next scheduled interval according to the instructions in M-0, Section 6-4.8.
 - a. Rather than drain the oil into catch basin and try to strain the spent oil through a paper filter, Continental recommends the following enhanced instructions:
 - 1) Place a pre-cleaned catch basin beneath the oil sump drain.
 - 2) Position a 1000 micron or less (approximately 0.040" or less) mesh screen in the catch basin to strain the oil sump contents. The 1000 micron stainless steel oil strainer (part number 2000) shown in Figure 2 is designed to fit the opening of a standard 5 gallon bucket. It is available for purchased from Arborfab.com. Arbor Fabricating, 14030 Tuttle Hill, Milan, MI 48160. (734) 626-5864.
 - b. Rinse the excess oil residue from the screen, retaining any fragments, particles, or sediment in the screen for analysis.




Figure 2. 1000 Micron Stainless Steel Oil Strainer


NOTE: The quick drain coupling orifice may trap debris and sediment material. To prevent entrapped material and allow collection of ferrous particles, Continental strongly recommends removing the non-magnetic oil plug (Part No. 532432) or quick drain coupling (Part Nos. 656122, 656995, or 658764) and installing a magnetic drain plug (Part No. 636376 or 656169) in the oil sump to attract and collect ferrous (iron) wear particulate and larger particles that could contaminate the lubrication system. The presence and collection of material on the magnetic drain plug can: 1) indicate an issue with certain engine components; 2) prevent damage to the oil pump and; 3) capture particles that could become lodged in the oil pressure relief-valve and result in a low oil pressure event. Not all engines are equipped with quick drain couplings or magnetic drain plugs - check engine illustrated parts catalog for applicability.

- c. Examine the strainer, drain plug and/or quick drain coupling for abnormal/excessive wear material, metal fragments, and debris to assess the engine condition. Metal fragments on the magnetic drain plug may indicate excessive wear or part damage.

If piston pin bushing material (see Figure 3) is recovered from an engine, remove the cylinders, pistons, and piston pins (no more than two cylinders at a time) to inspect the connecting rod piston pin bushings. In addition, the piston pin bushing must be inspected for condition each time a cylinder is removed for any reason.



**MAGNETIC OIL
DRAIN PLUG**



**CONNECTING ROD
AND BUSHING**

Figure 3. Typical Indications of Bushing Fragments

III. INSTRUCTIONS FOR CONTINUED AIRWORTHINESS (ICA)

This bulletin contains updates to the Instructions for Continued Airworthiness required under Title 14 CFR § 43.13(a). A copy of this bulletin must be inserted into the manuals listed in Table 1 of this bulletin until the data is incorporated into the manual by revision or the bulletin is superseded or canceled.

WARNING

Instructions for Continued Airworthiness in Section 10-9.4 of M-0, Standard Practice Maintenance Manual contain the instructions for the remaining Maintenance and Overhaul Manuals listed below. When performing Connecting Rod Inspection or Maintenance, use the instructions in M-0, Section 10-9.4.

Table 1. Applicable Engine ICAs

Document Number	Applicable Engine Model(s)	Section/ Subsection
M-0	Continental Spark-Ignited AvGas Engines	10-9.4
M-2	O200D	M-0, § 10-9.4
M-6 ¹	IO240A, B	15-7.9
M-7	IO360A, AB, AF, C, CB, D, DB, ES, G, GB, H, HB, J, JB, K & KB	M-0, § 10-9.4

Table 1. Applicable Engine ICAs

Document Number	Applicable Engine Model(s)	Section/ Subsection
M-8	LTSIO360E, EB, KB, & RB; TSI0360A, AB, B, BB, C, CB, D, DB, E, EB, F, FB, G, GB, H, HB, JB, KB, LB, MB, RB, SB	M-0, § 10-9.4
M-11 ¹	IO520B, BA, BB, C, CB, M & MB	19
M-16 ¹	IO550A, B, C, G, N, P & R	15-7.2.1
M-18	TSIO550A, B, C, E, G, J, K & N	M-0, § 10-9.4
M-22 ¹	IOF240B	15-6.2.1
OH-15 ¹	TSIOL550C	16 & 18
OMI-15 ¹	TSIOL550C	16
OH-24 ¹	IOF550B, C, N, P & R	9-7.2.3
M-26 ¹	TSIOF550D, J, K & P	15-7.2.1
X30008 ¹	A-65	9
X30010 ¹	C-75, C85, C90 & O200A, B	XIII
X30013 ¹	C-125, C-145 & O300	10
X30016 ¹	E-165, E-185, E-225	IX
X30019 ¹	GO300A, C, D & E	9
X30027 ¹	IO346	IX
X30144 ¹	TIARA	7
X30033 ¹	TSIO470	X
X30039 ¹	IO520A, B, BA, BB, C, CB, D, E, F, J, K, L, M & MB	6
X30045 ¹	GTSIO520C, D, F, H, K, L, M & N	IX
X30574 ¹	TSIO520B, BB, BE, D, DB, E, EB, J, JB, K, KB, L, LB, N, NB, UB, VB, & WB	72-20-20
X30575 ¹	TSIO520AE, AF, C, CE, G, H, M, P, R & T	72-20-20
X30586 ¹	O470A, B, E, G, J, K, L, M, P, R, S & U	72-20
X30588 ¹	IO470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V & VO	72-40
X30600 ¹	TSIOL550A	72-40
X30607 ¹	IO550D, E, F, L	72-40

1. The contents of these documents will be modified to reference M-0, Section 10-9.4.

IV. INSPECTION

CAUTION: Connecting rod piston pin bushing replacement requires specialized tools and procedures and must be accomplished by a shop properly rated to perform the repair.

NOTE: Complete Connecting Rod Piston Pin Inspection Criteria may be found in **Section 10-9.4.** of **M-0**, Standard Practice Maintenance Manual.

If piston pin bushing issues are suspected:

1. Remove the cylinders and pistons from the engine using the instructions contained in the appropriate maintenance or overhaul manual to gain access to the piston pin bushings.
2. Inspect the connecting rods according to the instructions in **M-0**, Section 10-9.4.
3. Visually inspect the piston pin bushing for any signs of cracks emanating from the piston pin bushing split line, missing bushing material, or signs of bushing movement.
4. Inspect the piston pin bushing for wear according to the instructions in **M-0**, Standard Practice Maintenance Manual, **Section 10-9.4.**
 - a. Replace any piston pin bushing that does not meet the installation criteria in **M-0**, Section 10-9.4 or is found cracked per during the inspection in step 3.
 - b. Replace any piston pin bushing that does not meet the inspection criteria in **M-0**, Standard Practice Maintenance Manual, **Section 10-9.4.**

V. WARRANTY

For engines currently within the warranty period, Continental will reimburse the customer for the parts and labor required to complete the inspection and repairs.

Intentionally Left Blank