



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: GFC 500 Autopilot System Owner and Operators
DATE: January 3, 2023
SUBJECT: Automatic Pitch Trim Enable
CERTIFICATION AUTHORIZATION: AML STC SA01866WI MDL Revision 77

COMPLIANCE

MANDATORY: This STC Service Bulletin must be accomplished within 6 months or at the next scheduled service interval; whichever occurs first.

PURPOSE

GFC 500 software allows pitch trim to be enabled as a closing action to Service Alert 22109 and STC Service Bulletin 22110.

PRODUCTS AFFECTED

GFC 500 Autopilot Systems with an optional GSA 28 Pitch Trim installed using STC SA01866WI, Master Drawing List 005-01264-00, Revisions 1 through 76 are affected.



NOTE

Cirrus SR20 and SR22 are not affected.

WARRANTY INFORMATION

This modification is warranty reimbursable with a deadline of June 30, 2023.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.